2. solder
3. component
4. componentmask
5. soldermask
6. plated-drill
7. topsilk
8. bottomsilk
9. bottompaste
10. toppaste
11. topassembly
12. bottomassembly
13. fab



back (mirrored), scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



front, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



frontmask, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



backmask (mirrored), scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



plated-drill, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



frontsilk, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb

backsilk (mirrored), scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb

backpaste (mirrored), scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



frontpaste, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb



frontassembly, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb

backassembly (mirrored), scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb

There are 5 different drill sizes used in this layout, 160 holes total

Symbol	Diam. (Inch)	Count	Plated?
˅	0.029	14	YES
+	0.035	128	YES
×	0.046	14	YES
°	0.062	2	YES
□	0.126	2	YES

Title: (unknown) - Fabrication Drawing
Author: Jelle de Jong
Date: Fri 15 May 2009 12:26:03 GMT UTC
Maximum Dimensions: 7874 mils wide, 9842 mils high



fab, scale = 1:1.000
/home/jelle/openarm/working/pcb/openarm-sbc.pcb

Board outline is the centerline of this 10 mil rectangle - 0,0 to 7874,9842 mils